


Erledigt Macbook Pro 13,3 2016 Wlan Probleme mit 5 GHz Funk

Beitrag von „al6042“ vom 17. Juni 2017, 22:38

Also, ich kann an meinem MBP13,3 keine Schw

Network	Address	Subnet	Gateway	Port	State	Speed	Power	Signal
Wi-Fi	192.168.1.10	192.168.1.0	192.168.1.1	802.11ac	Connected	1300 Mbps	0.00 W	-45 dBm
Thunderbolt 2	192.168.1.10	192.168.1.0	192.168.1.1	Thunderbolt 2	Connected	10 Gbps	0.00 W	-
Thunderbolt 1	192.168.1.10	192.168.1.0	192.168.1.1	Thunderbolt 1	Connected	10 Gbps	0.00 W	-
USB 3	192.168.1.10	192.168.1.0	192.168.1.1	USB 3	Connected	10 Gbps	0.00 W	-
USB 2	192.168.1.10	192.168.1.0	192.168.1.1	USB 2	Connected	480 Mbps	0.00 W	-
Bluetooth	192.168.1.10	192.168.1.0	192.168.1.1	Bluetooth	Connected	2.4 Mbps	0.00 W	-
Bluetooth LE	192.168.1.10	192.168.1.0	192.168.1.1	Bluetooth LE	Connected	1 Mbps	0.00 W	-
Cellular	192.168.1.10	192.168.1.0	192.168.1.1	Cellular	Connected	100 Mbps	0.00 W	-
Modem (Cellular)	192.168.1.10	192.168.1.0	192.168.1.1	Modem (Cellular)	Connected	100 Mbps	0.00 W	-
Modem (USB)	192.168.1.10	192.168.1.0	192.168.1.1	Modem (USB)	Connected	100 Mbps	0.00 W	-



Die drei umrahmten Netze gehören zu meinem TP-Link AC3200.

Die Performance Anzeige stammt vom eben, kurz nach dem Aufwecken.