

Erledigt

Cube Thinker i35 Hackintosh Kaby Lake

Beitrag von „orbislacteus“ vom 29. Juni 2017, 09:05

Zitat

I finally figured out what caused this. The plugins were not installed (which I knew and why this was baffling). Instead, there was a exception report stored in nvram that OSX always picked up. I think that happened because I decided to stop using EmuVariableUEFI.efi (which did work fine).

Ja, es sind andere CPUs, aber auch bei ihm wird irgendwas mit CPUSensors geladen, obwohl er keine kext drin hat und kein plugin.

Er schreibt das entfernen von emuvariableuefi hätte sein problem gelöst. Geht es auch ohne die? Ich schmeiß die jetzt mal raus ...