

Erledigt


Neubau nach Hardware austausch - Mein Erster Hackintosh

Beitrag von „Hontman“ vom 11. Juli 2017, 19:10

Soo... Habe jetzt beim starten von der Platte den InjectATI deaktiviert und startet immer noch im "Black screen" wenn ich vom stick boote ist alles gut, sogar Sound über HDMI von der Grafikkarte flutscht schon

Anbei ein Bild von der letzten Meldung die ansteht bevor er auf den Schwarzen Bildschirm springt. Scheint ein Problem mit AppleACPICPU zu geben?! Jemand einen Rat?

Das Problem mit den Farben wurde durch das SwitchResX und Millionen Farben erfolgreich behoben - Danke [@McRudolfo](#)!



```
AppleHDAController: Detected 16550HE/C/CF FIFO=16 M
Sound assertion in AppleHDAController at line 1434
Sound assertion in AppleHDA driver at line 1664
Sound assertion in AppleHDA driver at line 2324
Sound assertion in AppleHDA driver at line 2316
prevent idle sleep list: IOdisplayWrangler+ (1)
NTFS driver 3.13 [Flags: R/W].
NTFS volume name , version 3.1.
NTFS-fs error (device /dev/disk1s2, pid 131): ntfs_res
y.)
NTFS-fs error (device /dev/disk1s2, pid 131): ntfs_res
y.)
NTFS-fs warning (device /dev/disk1s2, pid 131): ntfs_log
Sound assertion in AppleHDA driver at line 3747
Sound assertion in AppleHDA driver at line 1090
busy timeout(0). (60s). kextd wait(0): 'AppleACPICPU'
```