

Erledigt

AppleALC kext patch request

Beitrag von „floris“ vom 14. November 2017, 23:22

It seems there is a solution. It works.

The Realtek ALC 671 is like an ALC 662 (Open Source Code Definition from Fujitsu to Linux Kernel Sources). And for the ALC 662 there is a Solution. (See How to Enable/Fix Realtek ALC 662 Audio Codec on macOS Sierra | Hackintosh at youtube)

"Realtek ALC662 Audio Fix.zip"

Installation: Drag the kext-File to the app, restart.

<https://drive.google.com/file/...lhDd3RTJPQTBvcGt2VTQ/view>

VendorID: 10EC DeviceID: 0671

DPCIManager shows

Audio Device Sub Device Codec ID Revision Codec Name

0x80868D20 0x17341215 0x10EC0671 0x0001 Realtek (unknown)