

Erledigt

Kein Audio nach Sleep Alc1150 Sierra

Beitrag von „kuckkuck“ vom 19. Dezember 2017, 15:42

My BIOS is pretty special and modified for my needs... And no, I leave the OEM DSDT in the BIOS and modify it afterwards. Otherwise I would have to use OSDW Methods to differentiate between MacOS ACPI Code and the Code necessary for other OSs.

Did you try the Kext?