

Erledigt Hp 8470p Fixes!

Beitrag von „griven“ vom 15. Januar 2018, 23:37

Well crashing macOS without NullCPUPowerManagement.kext normally indicates a locked MSR-2 register. AppleIntelPowerManagement.kext (XCPM as well) depends on this register to be writable otherwise it'll throw a kernel Panic. To overcome this issue in your case probably the best solution is to use Clover to overcome it. If you use CloverConfigurator navigate to Kernel and Kext Patches and tick AppleIntelCPUPM and save. Remove NullCPUPowerManagement.kext and reboot you should be good to go.