

Erledigt Hp 8470p Fixes!

Beitrag von „griven“ vom 16. Januar 2018, 00:11

Talking about Handoff some things have to be taken care about...

Bluetooth has to be at least BT 4.0 better 4.0LE an preferable internal USB Dongles might work but there is no guarantee of it. Also WLAN needs to meet some requirements since Handoff requires at least a WIFI Board which is compatible with the WIFI ac Standard which the AR9285 is unfortunately not. If you need Handoff, Continuity and stuff like that consider to replace your WIFI Card with something more compatible.