

Erledigt Hp 8470p Fixes!

Beitrag von „pole“ vom 20. Februar 2018, 21:35

Dear SapiGelo!

I created a bootable usb drive with UniBeast and I am on HFS+, not apfs!
(Copy the latest apfs.efi to drivers64UEFI if you..)
for HFS+: /Volumes/Image\ Volume/No-Convert (more on google)

You will need a new own SSDT, generate it with ssdtPRGen.sh.
(I used that command : './ssdtPRGen.sh -c 3')
<https://github.com/Piker-Alpha/ssdtPRGen.sh>

My Clover version is 4411 and all kexts are up to date.
(Update with Kext Updater By H-Forum - Respect to Sascha_77!)

Read the previous posts before you ask.

I hope it goes well, good luck!

Edit:-Updated the patched folder, little bit better fan behavior.