

Erledigt

Will Only Boot when I target thru the Bios

Beitrag von „griven“ vom 7. März 2018, 22:34

The ignorance of any set boot priority is a very common issue with OZ and some Bios Revisions.

You may try the F10 revision as well since the F10 revisions of Gigabytes Z77/H77 Boards are known to work as intended (working NVRAM). The Sleep issues may need some DSDT tweaking as well as some further Informations eg. WakeReason and stuff like that...