

Erledigt

Mac osx startet nach Installation nicht!

Beitrag von „Wege2003“ vom 7. Dezember 2018, 16:57


```
DYLIB_FIPS_POST: LCDH_POST passed!
DYLIB_FIPS_POST: FFDH_POST passed!
DYLIB_FIPS_POST: DRBG_CTR_POST passed!
DYLIB_FIPS_POST: DRBG_HMAC_POST passed!
DYLIB_FIPS_POST: FIPS_USER Space POST Success!
Waiting for DSMOS...
IOGraphics flags 0x43
Previous shutdown cause: 5
Apple16X50ACPI0: Identified Serial Port on ACPI Device=UAR1
HID: Legacy shim 2
DSMOS has arrived
HID: Legacy shim 2
prevent idle sleep list: IODisplayWrangler+ (1)
HID: Legacy shim 2
Apple16X50UARTSync0: Detected 16550AF/C/CF FIFO=16 MaxBaud=115200
unexpected session: 100000 uid: -1 requested by: 28
AppleKeyStore: operation failed (pid: 28 sel: 7 ret: e00002c2 '-536870206', -1, 100000)
ACPI_SMC_PlatformPlugin::start - waitForService(resourceMatching(AppleIntelCPUPowerManagement
ACPI: Dynamic OEM Table Load:
ACPI: SSDT 0xFFFFF8030C53690 0003FF (v02 PmRef Cpu0Cst 00003001 INTL 20160422)
ACPI: Executed 1 blocks of module-level executable AML code
ACPI: Dynamic OEM Table Load:
ACPI: SSDT 0xFFFFF8031703810 000693 (v02 PmRef Cpu0Ist 00003000 INTL 20160422)
ACPI: Executed 1 blocks of module-level executable AML code
WARNING: IOPlatformPluginUtil : getCPUIDInfo: this is an unknown CPU model 0x9e
-- power management may be incomplete or unsupported
ACPI: Dynamic OEM Table Load:
ACPI: SSDT 0xFFFFF803018A010 00065C (v02 PmRef ApIst 00003000 INTL 20160422)
ACPI: Executed 1 blocks of module-level executable AML code
ACPI: Dynamic OEM Table Load:
ACPI: SSDT 0xFFFFF8031ECDE10 00018A (v02 PmRef ApCst 00003000 INTL 20160422)
ACPI: Executed 1 blocks of module-level executable AML code
IOConsoleUsers: time(0) 0->0, lin 0, llk 1,
IOConsoleUsers: gIOScreenLockState 3, hs 0, bs 0, now 0, sm 0x0
```

Hallo wie unten auf dem Bild zu sehen ist steckt der Bootvorgang beim installierten Mac Osx Sierra es tut sich nichts mehr!

Bitte

um

Hilfe



es wurde bereits auf der SSD installiert und steckt jetzt hier bitte um Hilfe