

Erledigt

Dell XPS 9550 Soundprobleme

Beitrag von „rubenszy“ vom 15. Dezember 2018, 14:25

Bei der config würde ich erst mal anfangen, SMBios ist bei beiden verkehrt, sie arbeiten doch schon mit einem CPU der Apple verbaut hat, dann kann man das SMBios auf diesen Fahren lassen.

Keywords=MacBookPro13,3

Showing 1 - 3 of 3

[MacBook Pro "Core i7 2.8 15" TouchLate 2016](#) 2.8 GHz Core i7 (I7-6700HQ)

| | | | |
|---------|---------------------------|---------|------------------|
| Info | October 27, 2016 | Doc | June 5, 2017 |
| Order | MLH3LLK* | Model | A1707 (SMC 3072) |
| Family | Late 2016 15" (Touch Bar) | ID | MacBookPro13,3 |
| RAM | 16 GB | VRAM | 2 GB* |
| Storage | 256 GB SSD* | Optical | None* |

[Complete MacBook Pro "Core i7 2.8 15" TouchLate 2016 Specs](#)

[MacBook Pro "Core i7 2.7 15" TouchLate 2016](#) 2.7 GHz Core i7 (I7-6620HQ)

| | | | |
|---------|---------------------------|---------|------------------|
| Info | October 27, 2016 | Doc | June 5, 2017 |
| Order | MLH3LLK* | Model | A1707 (SMC 3072) |
| Family | Late 2016 15" (Touch Bar) | ID | MacBookPro13,3 |
| RAM | 16 GB | VRAM | 2 GB* |
| Storage | 512 GB SSD* | Optical | None* |

[Complete MacBook Pro "Core i7 2.7 15" TouchLate 2016 Specs](#)

[MacBook Pro "Core i7 2.8 15" TouchLate 2016](#) 2.9 GHz Core i7 (I7-6820HQ)

| | | | |
|---------|---------------------------|---------|------------------|
| Info | October 27, 2016 | Doc | June 5, 2017 |
| Order | 8T0C7D | Model | A1707 (SMC 3072) |
| Family | Late 2016 15" (Touch Bar) | ID | MacBookPro13,3 |
| RAM | 16 GB | VRAM | 2 GB* |
| Storage | 256 512 GB SSD* | Optical | None* |

[Complete MacBook Pro "Core i7 2.8 15" TouchLate 2016 Specs](#)