

AppleALC - der dynamische AppleHDA Patcher - immer aktuell

Beitrag von „Noir0SX“ vom 2. Januar 2019, 15:05

v1.3.4

- Disabled AppleGFXHDA matching onto HDEF to force AppleHDA usage
- Added Wern Apfel's menubar patch for CX20590
- Added ALC255 layout-id 21 for Asus X441UA-WX096D by Andres ZeroCross
- Added ALC255 layout-id 21 for Asus VivoBook Pro 15 CX8150 by Andres ZeroCross
- Added ability to disable controller injection with property `no-controller-inject`
- Added SigmaTel STAC9200 layout-id 11 for Dell Precision 390 by Goldfish64
- Added support for HDMI Audio of Alienware Alpha GTX860M
- Added ALC1220 layout-id 15 for MSI WT75 Laptop by fleaplus.
- Fix ConfigData in ALC256 (3246) for Dell Series by Insanelydeepak
- Added ALC298 layout-id 21 for Lenovo 720S-15IKB by Andres ZeroCross
- Added ALC236 layout-id 99 for Lenovo Air 13 IWL by DalianSky
- Fix speaker volume slider CX8050
- Enable NVIDIA HDMI patches for laptop GPUs
- Added ALC280 layout-id 21 for Dell Precision T7610 Workstation by Andres ZeroCross
- Added ALC295 layout-id 21 for Acer Nitro 5 Spin (NP515-51) by Andres ZeroCross
- Added VIA VT1705 layout-id 21 for ECS H81H3-M4 (1.0A) by Andres ZeroCross
- Added ALC269 layoutid=88 for MECHREVO X8Ti Plus by DalianSky
- Added ALC662 layout-id 17 for HP Compaq Elite 8000 SFF by aloha_cn
- Added ALC288 layout-id 23 for Dell XPS 9343 by yyfn
- Added ALC892 layout-id 16 for MSI GL73-8RD by MacPeet
- Change CX20585 layout-id 13 resources
- Added ALC887 layout-id 52 for Asus PRIME Z270-P by ctich
- Added AD1984A layout-id 44 by Giesteira
- Added ALC269 layout-id 44 for Samsung _NP350V5C by Giesteira
- Added ALC269 layout-id 17 by MacPeet
- Added ALC1220 layout-id 16 for Gigabyte Z390 by MacPeet