

Erledigt

Designare Z390 / i9 9900 K / Radeon Vega 64 - EFI File Problem ?

Beitrag von „JimSalabim“ vom 13. September 2019, 15:22

Ich hab meine im unteren, also dem M2P. Andere schreiben, sie haben sie im oberen, also dem M2M. Eigentlich sollte es egal sein.

Man muss nur hierauf achten:

Installation Notices for the M.2 and SATA Connectors:

Due to the limited number of lanes provided by the Chipset, the availability of the SATA connectors may be affected by the type of device installed in the M.2 sockets. The M2M connector shares bandwidth with the SATA3 4, 5 connectors. The M2P connector shares bandwidth with the SATA3 0, 1 connectors. Refer to the following tables for details.

M2M:

Type of M.2 SSD	Connector	SATA3 0	SATA3 1	SATA3 2	SATA3 3	SATA3 4	SATA3 5
M.2 SATA SSD		✓	✓	✓	✓	✗	✗
M.2 PCIe SSD		✓	✓	✓	✓	✗	✗
No M.2 SSD installed		✓	✓	✓	✓	✓	✓

✓ : Available, ✗ : Not available

M2P:

Type of M.2 SSD	Connector	SATA3 0	SATA3 1	SATA3 2	SATA3 3	SATA3 4	SATA3 5
M.2 SATA SSD		✓	✗	✓	✓	✓	✓
M.2 PCIe SSD		✗	✓	✓	✓	✓	✓
No M.2 SSD installed		✓	✓	✓	✓	✓	✓

✓ : Available, ✗ : Not available