


HowTo: Thunderbolt HotPlug/HotSwap Finetuning für euren Hackintosh

Beitrag von „Mork vom Ork“ vom 18. September 2019, 14:43

wie gesagt, ich flashe ein gemodded BIOS immer mit "fptw64.exe -BIOS -F Z37GIX_4.10"



```
Administrator: Eingabeaufforderung
C:\temp\FPTW64>FPTW64.exe -bios -f mod_Z170XSF.20K

Intel (R) Flash Programming Tool. Version: 11.8.55.3510
Copyright (c) 2007 - 2017, Intel Corporation. All rights reserved.

Reading HSFSTS register... Flash Descriptor: Valid

--- Flash Devices Found ---
MX25L12875F      ID:0xC22018      Size: 16384KB (131072Kb)

- Reading Flash [0x1000000] 14336KB of 14336KB - 100 percent complete.
- Erasing Flash Block [0x23E000] - 100 percent complete.
- Programming Flash [0x023E000] 248KB of 248KB - 100 percent complete.
- Erasing Flash Block [0x240000] - 100 percent complete.
- Programming Flash [0x0240000] 4KB of 4KB - 100 percent complete.
- Erasing Flash Block [0x298000] - 100 percent complete.
- Programming Flash [0x0298000] 4KB of 4KB - 100 percent complete.
- Erasing Flash Block [0x5F7000] - 100 percent complete.
- Programming Flash [0x05F7000] 632KB of 632KB - 100 percent complete.
- Erasing Flash Block [0xF5A000] - 100 percent complete.
- Programming Flash [0x0F5A000] 8KB of 8KB - 100 percent complete.
- Verifying Flash [0x1000000] 14336KB of 14336KB - 100 percent complete.
RESULT: The data is identical.

FPT Operation Successful.

C:\temp\FPTW64>
```