

# Neuer Rechner neue Hardware. Klappt das?

Beitrag von „friedrich“ vom 20. Oktober 2019, 16:17

Hallo Leute,

meine Installation bricht immer wieder ab. Kann es sein dass ich im BIOS noch wichtige Einstellungen vergessen habe?

LG

Stefan

```
CPUMemors: setting platform keys to [FD ]
FabricCpufw: key 1000 handler CPUMemors has been replaced with new prioritized handler CPUMemors
SMemors: (Error) unable to validate Dell SMM signature, not loading SMemors
FabricCpufw: key 1000 handler CPUMemors has been replaced with new prioritized handler CPUMemors
CPUMemors: load CPU multiplier is 28
CPUMemors: started

BIOS: Legacy mode 2
PCI: Only single SMM lock (128 bytes)
FabricCpufw: key 1000 handler CPUMemors has been replaced with new prioritized handler CPUMemors
BIOS: Legacy mode 2
FabricCpufw: (Warning) blocked while trying to set protected key "F10a"
FabricCpufw: 32 protected keys added
FabricCpufw: 2 keys supported by Clover EFI
SMCI: successfully initialized
Revision shutdown cause: 2
ms: Serial: 20:20:14 Sep 25 2019, Flags: 00b03000
I PCI configuration begin I
I PCI configuration end, bridges 11, devices 30 I
I PCI configuration begin I
I PCI configuration end, bridges 13, devices 60 I
I PCI configuration begin I
I PCI configuration end, bridges 19, devices 122 I
AppleMkInit failed: I PCI configuration end, bridges 19, devices 122 I
AppleMkInit failed: I PCI configuration end, bridges 19, devices 122 I
SuperMicro: Failed to load BIOS for device 11, device 30, flags 00b03000
SuperMicro: Failed to load BIOS for device 11, device 30, flags 00b03000
SuperMicro: Failed to load BIOS for device 11, device 30, flags 00b03000
SMCI: (Warning) wrong vendor ID=0xffff
CPUMemors: started
NFI Error: (TSSB) Response lookup failure, RE_MBT_FIRM (0x00000000/0x00)
[OSX] booting 0x00
No Local Variables are initialized for method (TSSB)
No Arguments are initialized for method (TSSB)
NFI Error: Method parameterization failed (L_30_P10_000) (Mask FFFFFFFF16a6660, RE_MBT_FIRM (0x00000000/0x00))
NFI Error: (TSSB) Response lookup failure, RE_MBT_FIRM (0x00000000/0x00)
[OSX] booting 0x00
No Local Variables are initialized for method (TSSB)
No Arguments are initialized for method (TSSB)
NFI Error: Method parameterization failed (L_30_P10_000) (Mask FFFFFFFF16a6660, RE_MBT_FIRM (0x00000000/0x00))
CPUMemors: started
```