

In Arbeit Installation von Catalina hängt

Beitrag von „Iron-phil“ vom 28. Oktober 2019, 18:40

Hallo Freunde des gepflegten Hackintoshs!

Ich habe ein neues Projekt: Elitebook 840 G5(i5-8350) mit Catalina aufwerten.

Ich habe schon gefühlt alles versucht, leider klappt jedoch die Installation nicht.

im Anhang mein EFI Ordner, sowie zwei Screenshots.


Anfangs klappt die Installation. Beim zweiten Boot, in die Datei Install from MacOS (also die interne NVMe SSD) tritt dann folgendes auf:

1. Zuerst wird ewig lange im Verbosemode angezeigt das APIC Fehler vorkommen.

Gemäss meiner Recherche immer wieder Embedded Controller, Battery und noch etwas, dass mir gerade nicht mehr einfällt.

Umbenennung von EC0 auf EC wird gemacht. SSDT-EC ist auch im Patched Ordner von Clover.

2. Kommt dann der Ladescreen und bleibt bei About 11 minutes remaining hängen.[EFI.zip](#)



```
Loaded: FFFFFFFF00000000 (0x0) 0x0000000000000000
Initialised Arguments For Method (00F7): (0 arguments defined for method (Initiation))
Arg: FFFFFFFF00000000 (0x0) 0x0000000000000000
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Exception: 00_00000000, Returned by Handler for [EmbeddedControl] Controller (signature=00)
00F7: 00000000 0x0

Initialised Local Variables for method (00F7):
Local0: FFFFFFFF00000000 (0x0) 0x0000000000000000
Local1: FFFFFFFF00000000 (0x0) 0x0000000000000000

Initialised Arguments For Method (00F7): (0 arguments defined for method (Initiation))
Arg: FFFFFFFF00000000 (0x0) 0x0000000000000000
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Exception: 00_00000000, Returned by Handler for [EmbeddedControl] Controller (signature=00)
00F7: 00000000 0x0

Initialised Local Variables for method (00F7):
Local0: FFFFFFFF00000000 (0x0) 0x0000000000000000
Local1: FFFFFFFF00000000 (0x0) 0x0000000000000000

Initialised Arguments For Method (00F7): (0 arguments defined for method (Initiation))
Arg: FFFFFFFF00000000 (0x0) 0x0000000000000000
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Exception: 00_00000000, Returned by Handler for [EmbeddedControl] Controller (signature=00)
00F7: 00000000 0x0

Initialised Local Variables for method (00F7):
Local0: FFFFFFFF00000000 (0x0) 0x0000000000000000
Local1: FFFFFFFF00000000 (0x0) 0x0000000000000000

Initialised Arguments For Method (00F7): (0 arguments defined for method (Initiation))
Arg: FFFFFFFF00000000 (0x0) 0x0000000000000000
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Exception: 00_00000000, Returned by Handler for [EmbeddedControl] Controller (signature=00)
00F7: 00000000 0x0

Initialised Local Variables for method (00F7):
Local0: FFFFFFFF00000000 (0x0) 0x0000000000000000
Local1: FFFFFFFF00000000 (0x0) 0x0000000000000000

Initialised Arguments For Method (00F7): (0 arguments defined for method (Initiation))
Arg: FFFFFFFF00000000 (0x0) 0x0000000000000000
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Error: Method parse/execution failed [\_SB.PCI0.LPCX.EC.00F7] (table FFFFFFFF00000000), @ 000_00000000 (0x00000000)
ACPI Exception: 00_00000000, Returned by Handler for [EmbeddedControl] Controller (signature=00)
00F7: 00000000 0x0
```

