


Erledigt

Funktioniert bei euch USB C 3.1 bzw. Thunderbolt 3?

Beitrag von „luxus13“ vom 3. Januar 2020, 20:04

Bei mir sieht es so aus:

```
pci 0000:00:14.0: Apple Thunderbolt 3 Bridge (Apple Ridge 4C 2016) bridge 001:0000  
pci 0000:00:14.1: Apple Thunderbolt 3 Bridge (Apple Ridge 4C 2016) bridge 001:0000  
pci 0000:00:14.2: Apple Thunderbolt 3 Bridge (Apple Ridge 4C 2016) bridge 001:0000  
pci 0000:00:14.3: Apple Thunderbolt 3 Bridge (Apple Ridge 4C 2016) bridge 001:0000  
pci 0000:00:14.4: Apple Thunderbolt 3 Bridge (Apple Ridge 4C 2016) bridge 001:0000  
pci 0000:00:14.5: Apple Thunderbolt 3 Bridge (Apple Ridge 4C 2016) bridge 001:0000  
pci 0000:00:14.6: Apple Thunderbolt 3 Bridge (Apple Ridge 4C 2016) bridge 001:0000  
pci 0000:00:14.7: Apple Thunderbolt 3 Bridge (Apple Ridge 4C 2016) bridge 001:0000  
pci 0000:00:14.8: Apple Thunderbolt 3 Bridge (Apple Ridge 4C 2016) bridge 001:0000  
pci 0000:00:14.9: Apple Thunderbolt 3 Bridge (Apple Ridge 4C 2016) bridge 001:0000
```



USB Controller:				
Type	Name	Serial	Vendor ID	Device ID
XHC	100 Series/C230 Series Chipset Family USB 3.0 xHCI Controller	105/C230	0x8086	0xA12F

USB Attached Mass Storage:				
Name	Connection	Protocol	Dev Speed	Dev ID
HSD1	USB3	Sx01	480 Mbps	
HSD3	USB3	Sx03	480 Mbps	Keyboard Hub
HSD4	USB3	Sx04	Unknown	
HSD5	USB3	Sx05	Unknown	
HSD6	USB3	Sx06	Unknown	
HSD7	USB3	Sx07	480 Mbps	
HSD8	USB3	Sx08	12 Mbps	2.4G RF Keyboard & Mouse
HSD2	Internal	Sx0C	12 Mbps	BRCM20702 Hub
SSD1	USB3	Sx11	5 Gbps	
SSD3	USB3	Sx13	Unknown	
SSD4	USB3	Sx14	Unknown	
SSD5	USB3	Sx15	Unknown	
SSD6	USB3	Sx16	Unknown	
USR1	TypeC-Su	Sx0F	Unknown	
USR2	USB3	Sx10	5 Gbps	