

# Gigabyte C621 Aorus Xtreme ALC1220VB Problem

Beitrag von „DSM2“ vom 9. Januar 2020, 01:24

You will find the "problem" in the name of the Audio Chip itself.

## ALC1220-VB2

It's unknown in AppleALC and that's the problem...