

Gigabyte C621 Aorus Xtreme ALC1220VB Problem

Beitrag von „kingcyk“ vom 10. Januar 2020, 01:31

@[apfelnico](#) It seems a simply rename from CAVS to HDEF? I've tried in clover rename but can't get it work. Besides, applealc's wiki shows better not do rename I think.

@[MacPeet](#) to be honest I tried these id twice. all of them can't work. and I tried two ways suggested by applealc wiki 1. boot arg alcid=xx and 2. device property or ssdt layout-id like 0B000000. can't work.

Alright, I solved this by spoof the device to 8086:a170. weird.



I tried 8086:a2f0 first but nothing happed.