

Erledigt

DW-1820a /

Broadcom

BCM94350ZAE

Verbindungsproblem

Beitrag von „MacPeet“ vom 12. Januar 2020, 17:50

Ich nutze den bereits, aktuell mit Catalina:

```
Scope (_SB.PCI0.EXP2)
```

```
{
```

```
Device (ARPT)
```

```
{
```

```
Name (_ADR, Zero) // _ADR: Address
```

```
Name (_PRW, Package (0x02) // _PRW: Power Resources for Wake
```

```
{
```

```
0x09,
```

```
0x04
```

```
})
```

```
Method (_DSM, 4, NotSerialized) // _DSM: Device-Specific Method
```

```
{
```

```
Store (Package (0x0E)
```

```
{
```

```
"model",
```

```
Buffer (0x25)
```

```
{
```

```
"Broadcom DW1820A a/b/g/n/ac Wireless"
```

```
},
```

"device_type",

Buffer (0x08)

{

"AirPort"

},

"built-in",

Buffer (One)

{

0x00

},

"name",

Buffer (0x10)

{

"AirPort Extreme"

},

"AAPL,slot-name",

Buffer (0x09)

{

"Internal"

},

"compatible",

Buffer (0x0D)

```
{  
"pci14e4,4331"  
},  
  
"pci-aspm-default",  
Buffer (One)  
{  
0x00  
}  
, Local0)  
DTGP (Arg0, Arg1, Arg2, Arg3, RefOf (Local0))  
Return (Local0)  
}  
}
```

...und keine KP's beim Booten, auch keine Freeze's nach einer Stunde, wie so oft beschrieben in den Foren.