


In Arbeit



AMD Phenom(tm) II X6 1100T Processor mit SABERTOOTH 990FX kein update möglich auf neue OS

Beitrag von „Nobody_iOS“ vom 25. Februar 2020, 00:47

Kann wer etwas Erkennen a



Hier noch der Boot in Fotos.



```

Configuration:
Boot Signing: disabled
Filesystem Protections: disabled
Task for PID: disabled
Debugging Restrictions: enabled
Apple Internal: enabled
STrace Restrictions: disabled
NUVM Protections: disabled

- Decompressing Kernel Using lzma
[ KERNEL PATCHER START ]

Will patch for 15.0.0 kernel version.

KernelBooter_Exit state: enabled!
KernelPm state: disabled!
KernelLapicError state: disabled!
KernelLapicVersion state: disabled!
KernelHawaii state: disabled!
KernelCpuFamily state: disabled!
KernelSSE3 state: disabled!
- Searching for booter extensions pattern:
Found Ki Capitan pattern, patched!

```

```

KernelCpuFamily state: disabled!
KernelSSE3 state: disabled!
- Searching for booter extensions pattern:
Found Ki Capitan pattern, patched!
1 substitution(s) made.
Kernel has successfully patched.

No DSDT found, using 0 as uid value.
Using PCI-Root-UID value: 0
[ ATI GFX DEVICE INFO ]
Class code: {0300}
Video BIOS read from file

[ ETHERNET DEVICE INFO ]
Class code: {0200}
EthernetBuiltIn = Yes
Location number: 1
Setting up Lan Args
Realtek RTL8111/0150 PCI-E Gigabit Ethernet (10ec:0150)
PciRoot(0x0)/Pci(0x15,0x1)/Pci(0x0,0x0)

[ ACPI PATCHER ]
Adding booter spec to the Platform Expert
Attempting to load drivers from "Extra" repository:
0

```