

Erledigt Thunderbolt problem?

Beitrag von „Extreme“ vom 16. Mai 2020, 13:21

Hi!

I used the wonderful DSM2 guide to install Catalina and to optimize the post installation. Everything works except thunderbolt. When I start catalina and check the info menu on this mac / system report / PCI no thunderbolt entry is read. Is it normal or there is some problem. I specify that on windows 10 thunderbolt works perfectly.

I attach the Efi in use and my ioreg.

Thanks for helps.

My hardware:

Anidees AI Crystal XL AR 3

Asus WS X299 SAGE/10G

Intel Core i9-7980XE

Noctua NH-U12A

AMD Radeon™ VII

Crucial Ballistic Sport 3200 Mhz 128 GB

Gigabyte GC-TITAN RIDGE

caldigit ts3 plus

Sabrent 1TB Rocket NVMe PCIe M.2 2280 - macOS Catalina

Sabrent 1TB Rocket NVMe PCIe M.2 2280 - Windows 10

Download EFI:

<http://www.mediafire.com/file/mon1kr16bazz9pq/EFI.zip/file>

Download loreg:

http://www.mediafire.com/file/...ac_Pro_di_Enrico.zip/file

