

HP EliteBook 840 G1 & OpenCore Catalina/Big Sur

Beitrag von „xerano“ vom 27. Juli 2020, 08:45

[Zitat von vivandi](#)

BIOS Settings

Spam the F10 key

Go to Advanced

- Device configuration
 - Don't check Fn key switch (it has to be unchecked in order to the volume and brightness hotkeys work)
 - Change Video memory to 128MB
 - Disable wake on USB
 - Disable Virtualization Technology (VT-x)
 - Set SATA to AHCI
- Built in device option
 - Disable Wake on LAN

Save and reboot in UEFI.

Das war was ich bei Mojave gemacht habe!!

Bei dem EFI Ordner von Sandroo fehlt die Bluetooth Unterstützung!!

Alles anzeigen

Ja er hat die BRCMPatchRAM3.kext nicht drin deshlab klappt das nicht.