

AirportBrcmFixup Patch Sammlung für Broadcom Airport Wi-Fi Karten

Beitrag von „Noir0SX“ vom 3. August 2020, 17:18

v2.0.8

- Added constants for 11.0 support
- Property 'pci-aspm-default' with value 0 is not required for Broadcom BCM4350 chipset (with non-apple subsystem-vendor-id), since now it is injected/corrected and method IOPCIFamily::setASPMState called for provider to disable ASPM immediately.
- Add required dependencies into OSBundleLibraries section
- Remove injectors for AirPortBrcm4360 and AirPortBrcmNIC from main Info.plist and move them into separate plugins AirPortBrcm4360_Injector and AirPortBrcmNIC_Injector (kexts with plist only).
Under 10.16 (Big Sur) plugin AirPortBrcm4360_Injector.kext must be blocked by MaxKernel 19.9.9 or just removed, otherwise it will block loading of AirPortBrcmNIC since class AirPortBrcm4360 is unsupported.
- Check whether brcmfxf-driver value is incorrect (if specified value is unsupported in current osx system)
- Support boot-arg and property `brcmfxf-aspm` to override value used for pci-aspm-default