

Suche Ryzen OC config - BigSur läuft auf AMD FX 6300


Beitrag von „Franziska1993“ vom 29. August 2020, 12:25

Sowas gibt es, aber jsl2000 arbeitet mit Shaneee zusammen an patches, ich glaube nicht, das er sich mit "Blendern" abgibt.

Ich glaube es liegt entweder an den cpu-patches, die eben nur für Catalina gedacht sind oder an der Kombi AMD FX und NVIDIA.

Später poste ich dir ein Screenshot mit einer Fehlermeldung, die diese Vermutung unterstützt.

Bis nachher....



```
Fri Aug 28 21:00:07 2020 localhost com.apple.xpc.launchd[1]
Fri Aug 28 21:00:07 2020 localhost com.apple.xpc.launchd[1]
Fri Aug 28 21:00:07 2020 localhost com.apple.xpc.launchd[1]
Fri Aug 28 21:00:07 2020 localhost com.apple.xpc.launchd[1]
Fri Aug 28 21:00:07 2020 localhost com.apple.xpc.launchd[1]
Fri Aug 28 21:00:07 2020 localhost com.apple.xpc.launchd[1]
IOConsoleUsers: gIOScreenLockState 3, hs 0, bs 0, now 0, sm
GTrace synchronization point 48
syncing disks... Killing all processes

continuing
apfs_stop_bg_work:935: System is shutting down stop any bg w
hfs: unmount initiated on Shared Support on device disk6s2
apfs_vfsop_unmount:2135: disk2: unmounting volume 'test'
apfs_vfsop_unmount:2166: waiting for cleaners to finish: pur
rx_volume_group_update:6539: Volume test role 0 Not a System
dev_dump:256: Aggregate destructed: dev=<ptr> dl=0 dv_num_sl
apfs: total mem allocated: 5261588 (5 mb);
apfs_vfsop_unmount:2463: all done. going home. (numMounted
hfs: unmount initiated on Install macOS Beta on device disk1
apfs_vfsop_unmount:2135: disk5: unmounting volume 'Preboot'
rx_volume_group_update:6539: Volume Preboot role 10 Not a Sys
disk5: 0x5 (UNDEFINED).
rx_buf_bread:595: buf_blowait() failed: errno = 5, h...
```

Dieses IOConsoleUsers: gIOScreenLockState 3 usw. lassen mich vermuten, dass es irgendwie mit der Grafik zutun hat.

Wie gesagt, vermuten, nicht wissen.....