

X299 Tutorial - ASUS WS X299 SAGE/10G (Hilfe und Diskussionen)

Beitrag von „Extreme“ vom 24. September 2020, 07:28

From bios 3000 versions onwards there are problems in the management of the ram frequency. These problems do not occur with bios versions 2002 and lower in the Sage 10G. I did the tests with 2 types of ram of different brands and both with the crucial ballistix sport (128 GB) and with the Corsair Dominator Platinum RGB (128) if the frequency is set to 3200 Mhz the problem of code 00 occurs with start-up cold: bios 3203. Returning the frequencies to default, in both cases the cold start does not give problems. There is therefore no failure in either the CPU or the motherboard but these are problems related to the latest Asus bios versions. For this reason, i am using bios 2002 which works very well both in general and in memory frequency management. Probably best bios version for the Sage 10G at the moment.