

HP EliteBook 840 G1 & OpenCore Catalina/Big Sur

Beitrag von „Zayed4502“ vom 3. Oktober 2020, 19:59

[Zitat von jboeren](#)

[Zayed4502](#) SIP should be 0x3E7 as discussed [here](#)

[user = '64831'] Razor12 [/ user] No video problems on Youtube.

Edit

Blg Sur 11.0 bèta (20A5384c) updated ohne Probleme 😊

Alles anzeigen

jboeren I have set the [sip](#) back to 0x3E7, I just forgot to trn on [sip](#) when updating macos, but the problem now is that the microphone is not getting any input.

[mhk](#) I am attaching my efi folder, try this see if it works with the battery it works with my battery when I replace them, I am linking a clover and a opencore, add your smbios