


Acer V5 573G - OpenCore - Catalina 10.15.6 - Audio/HDMI/Shutdown Probleme

Beitrag von „Claus59“ vom 10. Oktober 2020, 10:04

[Karatekid](#) ,

probiere mal diese Einstellungen:

A screenshot of a configuration file (likely OpenCore.plist) showing several settings. The settings are listed in a table-like format with their values and data types. The values are: AAPL,ig-platform-id: 0000160A; device-id: 02680000; disable-external-gpu: 01000000; framebuffer-fbmem: 00009000; framebuffer-patch-enable: 01000000; framebuffer-stolenmem: 00003001; framebuffer-unifiedmem: 00000080. The data types are all listed as 'DATA'.

AAPL,ig-platform-id	0000160A	DATA
device-id	02680000	DATA
disable-external-gpu	01000000	DATA
framebuffer-fbmem	00009000	DATA
framebuffer-patch-enable	01000000	DATA
framebuffer-stolenmem	00003001	DATA
framebuffer-unifiedmem	00000080	DATA

das koennte eventuell passen.

MfG Claus