

ASUS Rampage VI Extreme (original) with Radeon VII

Beitrag von „Warbands“ vom 22. Oktober 2020, 22:51

Thank you for the warm welcome! DSM2 I was about to handle my USB port mapping. I have seen 2 main methods for this.

Method # 1 InjectAll and Hackintool

<https://www.youtube.com/watch?...channel=OlarilaHackintosh>

Method # 2 Using USBMap

After watching the video for Method # 1, it seemed straight forward. I found USBMap in the past to be a bit hit and miss. Which method do most people use?

I have included my EFI, though this is ahead of me finishing the USB port mapping.

[juantrix](#) ,what is not currently working for you for your setup?

Edit, I ended up using USBMap as Method #1 ended up acting odd.

Damn there are alot of USB ports on this board 😊

I was able to bring my ports down to 15 according to USBMap