

# Lenovo Thinkpad T530

Beitrag von „5T33Z0“ vom 28. Oktober 2020, 11:59

[antukst](#)

Disable Acpi > SSDT-PM. It's not for your CPU Model.

Disable Acpi > DSDT during install.

Disable Virtualization

Disable Safe Boot

Disable Fingerprint Sensor

Disable Express Card Slot

Disable WWAN

Install latest BIOS for your Device <https://pcsupport.lenovo.com/u...d-t530/downloads/ds029246>

Try another SSD

I installed BigSur 3 days ago without any issues. You tried 4 different EFI Folders already and none of them Work... something must be wrong.