

Lenovo Thinkpad T530

Beitrag von „5T33Z0“ vom 28. Oktober 2020, 16:48

[Zitat von antukst](#)

NO JUST COPPY AND PAST AND USE

WRONG. You need to change the SMBIOS for BigSur to MacBookPro11,1 or 11,2 or 11,4 check everymac.com for CPU similar to your model in frequeuncies