

Bootfehler OC ASRock B75M + Finetuning

Beitrag von „5T33Z0“ vom 1. November 2020, 13:09

[bluebyte](#)

Kurze Info, zu ACPI > Delete Patches bei IvyBridge Prozessoren:

Die beiden Patches, "**CpuPm**" und "**Cpu0Ist**" sollen nur solange an bleiben, solange man noch keine eigene SSDT erstellt hat. Danach soll man sie ausschalten. Das ist im Sanity Checker falsch deklariert, dass die an sein sollen.

Dazu der Guide:

"Initialling with OpenCore's setup in the Ivy Bridge section, **we recommended users drop their CpuPm and Cpu0Ist to avoid any issues with AppleIntelCPUPowerManagement.kext. But dropping these tables have the adverse affect of breaking turbo boost in Windows.** So to resolve this, we'll want to keep our OEM's table but we'll want to add a new table to supplement data only for macOS. So once we're done creating our CPU-PM table, we'll re-add our OEM's CPU SSDTs."

Und später, nachdem man die SSDT-PM erstellt hat, heißt es:

"Finally, **we can disable our previous ACPI -> Delete entries (Enabled set to NO)!**"

Quelle: <https://dortania.github.io/Opene...y-bridge-power-management>