

NUC8i3BEH findet kein USB Boot

Beitrag von „5T33Z0“ vom 5. November 2020, 17:29

"Update to latest (0085) BIOS -> load BIOS defaults -> click advanced and change;"

<https://downloadcenter.intel.c...OS-Update-becfl-357-86-a->

Bitte BIOS Version prüfen.

Einstellungen prüfen:

Code

1. Devices -> USB -> Port Device Charging Mode: off
2. Security -> Thunderbolt Security Level: Legacy Mode
3. Power -> Wake on LAN from S4/S5: Stay Off
4. Boot -> Boot Configuration -> Network Boot: Disable
5. Boot -> Secure Boot -> Disable