

HP EliteBook 840 G1 & OpenCore Catalina/Big Sur

Beitrag von „Zayed4502“ vom 14. November 2020, 21:42

I removed USBPorts.kext and it works successfully rn but I am working on the battery. I cant seem to get it to detect the battery. I am using SMCBatteryManager.kext. I am switching back from ACPIBattery