

macOS Big Sur - Released

Beitrag von „kru102“ vom 14. November 2020, 23:53

Hallo,

Mein T440s bleibt bei diesem Punkt in einer Rebootschleife hängen. kann mir da vielleicht jemand helfen ? Boote mit OC 0.6.3.

```
Mac OS version:
Not yet set

Kernel version:
Darwin Kernel Version 20.1.0: Set Oct 31 08:07:11 PDT 2020; root:xnu-7195.50.7~2/RELEASE_ARM_T8020
Kernel UID: 0x00000000-0002-333F-3439-502098C365M
KernelCache slide: 0x00000000c4000000
KernelCache base: 0xffffffff000c500000
Kernel slide: 0x00000000c4100000
Kernel text base: 0xffffffff000c510000
__HIB text base: 0xffffffff000c500000
System model name: MacBookPro11,1 (Mac-1098D4F97305FFC)
System shutdown began: NO
Panic diagnostics file unavailable, panic occurred prior to initialization
Hibernation exit count: 0

System uptime in nanoseconds: 4131856433
Last Sleep:          absolute          base_nsec          base_nsec
Uptime   : 0x00000000f7fd57c8
Sleep    : 0x0000000000000000 0x0000000000000000 0x0000000000000000
Wake     : 0x0000000000000000 0x00000000f4c5bc3d 0x0000000000000000

== In Memory Panic Stackshot Succeeded == Bytes Traced 11676 (Uncompressed 33232) ==
Attempting system restart...
IOPlatformPanicAction -> AppleNKEIOKitDriver
IOPlatformPanicAction -> AppleGMC
IOPlatformPanicAction -> AppleNKEIOKitDriver
IOPlatformPanicAction -> AppleGMC
```