wlan BCM94331CD OpenCore0.6.4 BigSur Ryzentosh

Beitrag von "GenuineJakob" vom 22. Dezember 2020, 21:57

EDIT: Anscheinend wird die Karte in BigSur nicht mehr unterstützt, schaut mal hier: https://www.hackintosh-forum.de/forum/thread/51969

Hi, habt ihr die Karte denn mal mit einem anderen Betriebssystem getestet?

Ich habe so ziemlich den gleichen Adapter und bei mir wurde die Karte von meinem Mainboard aus nicht erkannt, unabhängig des Betriebssystems. Ich hatte mich damals bei ASRock gemeldet und die haben mir innerhalb von 4 Tagen ein <u>BIOS Update</u> gebastelt.

Testet am besten mal ein anderes Betriebssystem, schaut im BIOS oder an einem anderen Rechner.

Beta BIOS

Please read below information
ASRock Beta version BIOS are designed for the users who are seeking to achieve the best performance out of their PCs such as gamers, overclocking lovers and PC enthusiasts.
However, we don't recommend users to update BIOS while the system is running well. For any damages caused by improper operation of downloading or updating BIOS, ASRock assumes no responsibility. Before you download or update the BIOS, please read below (How to Update)* carefully. After updating BIOS, all the settings will be reset to the default.

Version	Date	Size	Update BIOS Under / How to Update	Description	Download	
[Beta] 2.50B	2017/12/18	5.19MB	Instant Flash	Enhance M.2 compatibility when using a PCIe to M.2 adapter. Enhance graphic card compatibility.	Global Global	China China
[Beta] 1.21D	2014/6/10	5.50MB	Instant Flash	Improve USB mouse compatibility under BIOS.	Global Global	China
[Beta] 1.01B	2014/5/7	5.47MB	Instant Flash®	Improve SATA Express performance.	Global	China
[Beta] 0.20G	2014/5/2	5.47MB	Instant Flash	Improve OC & performance.	Global	China China