

# ASUS Rampage VI Extreme (original) with Radeon VII

Beitrag von „Warbands“ vom 4. Januar 2021, 18:52

## [Zitat von Toskache](#)

You need a patch for the Aquantia:

\* com.apple.driver.AppleEthernetAquantiaAqtion

\* Find: 0F84C002 0000

\* Replace: 660F1F44 0000

When I use that patch, the 10Gb Ethernet disappears completely from the system information page. If I use the following patch it at least shows up, though it acts like I never have a cable plugged into it:

\* com.apple.driver.AppleEthernetAquantiaAqtion

\* Find: 6275696C 742D696E

\* Replace: 62626262 62626262

Under Windows 10 the Aquantia 10g Ethernet built into my ASUS Rampage VI Extreme works great with no issues.

I am noticing the following during bootup:

AssetMacros:

status,

file:/AppleInternal/BuildRoot/Library/Caches/com.apple.xbs/Sources/AppleEthernetAquantiaAqtion/AppleEthernetAqtion/AppleEthernetAquantiaAqtion/If\_axge.cpp, line: 5853, value: 0