

Neuer Hackintosh nach 6 Jahren - passt das für ne VIDEO Workstation ?

Beitrag von „CMMChris“ vom 9. Januar 2021, 16:53

Card shutting down with 100% fan spin is due to overheating. Fan going high speed when spinning up for cooling points at incorrect PowerPlay values for your card. You likely have a wrong value for the PWM. Wrong PWM value causes incorrect fan behavior which in turn causes overheating. Don't play with that stuff if you don't know what you are doing and use the card as is with stock settings. 😊