

Neuer Hackintosh nach 6 Jahren - passt das für ne VIDEO Workstation ?

Beitrag von „hannibal1969“ vom 10. Januar 2021, 02:02

[Zitat von CMMChris](#)

Wrong PWM value causes incorrect fan behavior which in turn causes overheating. Don't play with that stuff if you don't know what you are doing and use the card as is with stock settings.

I know what I'm doing. Pwm setting for nitro was mentioned to be 28 if i'm correct even told by you somewhere. I already tried all values in comment fields to be default. So everything to default. Even then it crashes under load. To be clear im happy in big sur without any device properties however the zero fan / turn on fan hysteresis is annoying. Maybe i should try it with other increased pwm value.