

DELL 7730 Big Sur ALC289 Layout ID

Beitrag von „ende4711“ vom 9. März 2021, 19:06

... geht leider nicht..

hier der Screenshot mit der 99 Layout ID:

The screenshot displays the 'Audio' section of macOS System Information. At the top, a table lists the device and sub-device information:

Device	Sub Device	Codec	Revision	Name
0x0386A175	0x10280832	0x108C2289	0x0000	ALC289
0x1002A0F5	0x10280832	-	-	Esperanza HDMI Audio (Radeon RX 470/480 / 570/580/590)

Below this is the 'Pin Configuration' table:

ID	PinDefault	Device	Connector	Port	Drive Location	Geometric Location	Color	S	P	SRP	
18 (0x12)	99460710	In	Mic In	Other Digital	Fixed	Internal	ATAP	Unknown	1	0	-
23 (0x17)	99170130	Out	Speaker	Other Analog	Fixed	Internal	ATAP	Unknown	3	0	-
25 (0x19)	00027000	Out	Line Out	1/4" Stereo/Mono	Jack	External	N/A	Black	0	0	-
33 (0x21)	01789310	FL+	HD Out	Pushbutton	Jack	External	Beze	Black	3	0	FL+

The 'Audio Info' section provides the following details:

- Name: Hant
- Class: AppleHDAudioDriver
- Manufacturer: Hant Corporation (048086)
- Device: 100 Series/C230 Series Chipset Family HD Audio Controller (0x4170)*
* You may require Special Audio Device ID
- Sub Vendor: Dell (0x1028)
- Sub Device: 777 (0x0832)
- Codec Vendor: Realtek (0x108C)
- Codec Name: ALC289 (0x0289)
- ALC Layout ID: 99
- Revision: 0x0000
- Min. Kernel: 13
- Max. Kernel: 15
- AFD Low Power State: <03000000>
- Codec ID: 0x108C2289
- Config Data: <01876032 08786032 02176032>

Womit das Microphone geht aber nicht der Ton.

evtl. hilft das weiter... oder es liegt an Big Sur 11.3 update...

Vielen Dank ...