

DELL 7730 Big Sur ALC289 Layout ID

Beitrag von „ende4711“ vom 14. März 2021, 13:43

Es geht alles perfekt.. kein knistern am Klinken Ausgang. Microphone geht mit Klinke als auch ohne Klinke mit Lautsprecher am Laptop.

Hier der Screenshot:

The screenshot displays the following information:

| Device | Sub Device | Codec | Revision | Name |
|------------|------------|------------|----------|--------|
| 0x1002A4F0 | 0x10290832 | 0x108C0289 | 0x0000 | ALC289 |

Hardware Name: Stereo HDMI Audio [Nahesee K3 471902 / 570380290]

Pin Configuration

| ID | PinOutback | Device | Connector | Port | Gross Location | Geometric Location | Color | D | P | SAMP | |
|-----------|------------|--------|-----------|------------------|----------------|--------------------|-------|-------|---|------|-----|
| 18 (0x12) | 90A60010 | In | MC In | Other Digital | Fixed | Internal | N/A | UNKN. | 1 | 0 | - |
| 20 (0x14) | 90170020 | Out | Speaker | Other Analog | Fixed | Internal | N/A | UNKN. | 2 | 0 | 0x2 |
| 25 (0x19) | 00811030 | In | Line In | 1/8" Stereo/Mono | Jack | External | N/A | Black | 3 | 0 | - |
| 33 (0x21) | 00211040 | Out | HP Out | 1/8" Stereo/Mono | Jack | External | N/A | Black | 4 | 0 | 0x2 |

Audio Info

| | |
|----------------------|---|
| Name | Wext |
| Class | AppleIOADriver |
| Manufacturer | Intel Corporation (0x8086) |
| Device | 100 Series/C230 Series Chipset Family HD Audio Controller (0x4170)* |
| Sub Vendor | * You may require Special Audio Device ID |
| Sub Device | 0x417028 |
| Sub Device | 777 (0x0B32) |
| Codec Vendor | Realtek (0x10EC) |
| Codec Name | ALC289 (0x0289) |
| ALC Layout ID | 15 |
| Revision | |
| Min. Kernel | 13 |
| Max. Kernel | 15 |
| HPD Line Power State | <03000000> |
| Codec ID | 0x108C0289 |
| Config Data | <01470402 02170402> |

Was wird noch benötigt?