

# Original MacBook Pro mid 2010 Boot-Problem nach Sommerzeitumstellung

Beitrag von „bluebyte“ vom 7. April 2021, 10:17

Letztendlich ist es jedem seine persönliche Angelegenheit, wenn man den möglichen Verlust verschmerzen kann.

Für einen Mac Mini 6,1 Ende 2012 ist Opencore für Big Sur gar nicht notwendig.

<https://www.maclife.de/news/tr...en-kriegen-100117055.html>

Partially compatible Mac models:

Mid 2010 white MacBook, 2010 13" MacBook Pro, 2010 MacBook Air: In addition to the features which don't work after initial installation on the 2011 13" MacBook Pros (Wi-Fi, sound, graphics acceleration, sleep, display brightness control), Ethernet doesn't work. The --2010 option for patch-kexts.sh (step 15) installs fixes for Wi-Fi, sound, and Ethernet, as well as drivers that enable the GeForce Tesla (9400M/320M) framebuffer (thereby fixing sleep and display brightness control). The framebuffer driver does not provide acceleration; the lack of graphics acceleration plus the relatively slow Penryn CPU means performance is sluggish. On at least some of these models, step 6 may fail with errors.