

Erledigt Wlan karte

Beitrag von „al6042“ vom 7. April 2021, 23:19

[Noobody](#)

Es macht keinen Sinn mehrere Threads zum gleichen Thema zu öffnen...

Laut der folgenden Webseite kannst du die Atheros Karten möglicherweise unter BS nutzen -> <https://osxlatitude.com/forums...ab=comments#comment-86614>

Im Detail:

Supported:												
Vendor	Model	Format	Ver-Dev	Chip	Rate	B1	B2	HJ	Ca	BB	OOD	Keat. (Driver)
0x11	0x1121	WLAN PCI	1000-0124	AR9280	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9280
0x11	0x1127	WLAN PCI	1000-0124	BCM43138	A/76/76/76	Y	Y	Y	Y	Y	Y	MacOSX/1000043138 patch
0x11	0x1128	WLAN PCI	1000-0124	BCM43138	A/76/76/76	Y	Y	Y	Y	Y	Y	MacOSX/1000043138 patch
0x11	0x1129	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x112A	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x112B	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x112C	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x112D	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x112E	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x112F	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x1130	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x1131	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x1132	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x1133	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x1134	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x1135	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x1136	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x1137	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x1138	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x1139	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x113A	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x113B	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x113C	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x113D	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x113E	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485
0x11	0x113F	WLAN PCI	1000-0124	AR9485	A/76/76/76	Y	Y	*	*	*	*	(+MacOSX) AR9485

Wobei die Erfolgsaussichten dünn sind:

Zitat

AR946x (168c,34), AR9485 (168c,32) and **AR9565** (168c,36) work to some degree (i.e. not 100%) with alternative (re-written) Atheros40 driver as posted at InsanelyMac by Chunnann. Further patching facility posted here. These cards appear very poorly supported to plain unsupported from High Sierra. They are NOT recommended.