

OpenCore startet funktionierende EFI nicht mehr - ist das Board hin ?

Beitrag von „taube111111“ vom 24. Juni 2021, 13:06

[griven:](#)

Danke für die Mühe, habe aber das gleiche Fehlerbild mit der Config. Habe einmal mit und ohne slide=0 getestet.

Hier sind wieder die logs:

Nach dem patchen des Kernels ist leider Ende.

```
15:878 ##-814 DCM: Patch success port com.apple.lokit.IDOSHostFamily
15:888 ##-813 DCM: Patching invalid size 40960 with 851840 for com.apple.driver.usb.AppleUSBXHCI
15:903 ##-813 DCM: 64-bit 0000000000000000 replace count = 1
15:924 ##-813 DCM: Patch success com.apple.driver.usb.AppleUSBXHCI
15:943 ##-813 DCM: Patching invalid size 204800 with 830880 for com.apple.driver.usb.AppleUSBXHCIPCI
15:957 ##-813 DCM: Skipping legacy port patch AppleUSBXHCIPCI on 210000
15:978 ##-813 DCM: 64-bit AppleIOMapper replace count = 1
15:984 ##-813 DCM: Patch success com.apple.lokit.IDPCIFamily AppleIOMapper
15:995 ##-813 DCM: Patch success dummy AppleIntelCPUPowerManagement
16:008 ##-852 DC: PreLinkd status = Success
16:008 ##-808 AAPL: #DBG_MM_ADDR[] Err[Bad] -- 00_MM_MCP
16:123 ##-825 AAPL: #DBG_LD_LKCP[] Err[Bad]
16:148 ##-825 AAPL: #DBG_LD_LKCP[] Err[Bad]
16:174 ##-825 AAPL: #DBG_ML_0_0_0x00_0x01_22_0x00
16:208 ##-825 AAPL: #DBG_ML_0_0_0x00_0x01_22_0x00
16:228 ##-825 AAPL: #DBG_ML_0_0_0x00_0x01_22_0x00
16:253 ##-825 AAPL: #DBG_STOP
16:273 ##-825 AAPL: #DBG_ML_0_0_0x00_0x01_22_0x00
16:298 ##-813 OCC: Setting os mode 8 -> 1
16:384 ##-813 AAPL: #DBG_DBG_EXIT 2821-06-24T12:59:24
16:393 1#-815 DC: Boot failed - Aborted
16:475 ##-156 KCM: StartImage failed - Aborted
```

Ich schaue später die logs auch mal genauer durch.