

HP EliteOne 800 G2 (Intel 6500 - Intel HD 530) - Framebuffer

Beitrag von „OSX-Einsteiger“ vom 23. Juli 2021, 22:14

Ich habe es korrigiert und eine andre AAPL,ig-platform-id 02001619 genommen.

Für das erste sollte es funktionieren muss es aber nicht .

Das mit der # ist auskommentiert .

```
Polk@polk:~/Hackintosh$ cat /etc/efi/boot/Apple/PlatformId.plist
AAPL,ig-platform-id      data      02001619
device-id                data      18180000
enable-hdmi-dividers-1x  data      01000000
enable-dpcc-max-link-rate-1x  data      01000000
framebuffer-patch-enable data      01000000
framebuffer-con0-enable  data      01000000
framebuffer-con0-index  data      00000000
framebuffer-con0-busid   data      00000000
framebuffer-con0-addr    data      13000000
framebuffer-con0-type    data      02000000
framebuffer-con0-flags   data      00000000
### framebuffer-con0-flags data      01000000
```

```
<02 00 00 00>    LVDS and eDP    - Laptop displays
<10 00 00 00>    VGA            - Unsupported in 10.8 and newer
<00 04 00 00>    DisplayPort    - USB-C display-out are DP internally
<01 00 00 00>    DUMMY          - Used when there is no physical port
<00 00 00 00>    HDMI
<00 00 00 00>    S-Video
<04 00 00 00>    DVI (Dual Link)
<00 02 00 00>    DVI (Single Link)
```