

# Anfrage aus dem HWC- Corebook X

Beitrag von „KMac“ vom 16. August 2021, 18:00

[lucahappy](#) full Installation Catalina, normal BIOSsettings (see Dortania) and after Installation I used USB-mouse to disable forcetrackpad in systempref. Changes in config as I marked inside ( serial etc.)