


```
gptefi:0:BIOS
[RE] enabled
[RE] init: enable enabled
Darwin Kernel Version 10.0.0; Tue Jun 7 16:33:36 PDT 2011; root:xnu-1504.15.3~
/so page bootstrap: 1002063 free pages and 30321 wired pages
loaded (limiting quantum is 10000 us
sig table max displ = 73
MultiCPUPowerManagement::init: properties=0x69a7740
MultiCPUPowerManagement::start
AppleACPICPU: Processor id=0 LocalApicid=0 Enabled
AppleACPICPU: Processor id=1 LocalApicid=1 Enabled
calling sso_policy_init for Quarantine
Security policy loaded: Quarantine policy (Quarantine)
calling sso_policy_init for Sandbox
Security policy loaded: Seatbelt sandbox policy (Sandbox)
calling sso_policy_init for TRSafetyNet
Security policy loaded: Safety net for Time Machine (TRSafetyNet)
Copyright (c) 1982, 1986, 1989, 1991, 1993
The Regents of the University of California. All rights reserved.

MPC Framework successfully initialized
using 16394 buffer headers and 4896 cluster ID buffer headers
Asynchronous I/O for cpu 1: 0x000000000a767552e, delta 0x50540
IDPIC: Version 0x20 Vectors 64:07
Current tsc from rdtscl( ) is 41504042200. Rendezvousing..
VoodooTSCSyn::doIsc(): stamp_tsc was called: 2 times
ACPI: System State (S0 S3 S4 S5) (S3)
PFMG4 0xf1000000, 0xf1000000
[ PCI configuration begin ]
PCI configuration changed (bridge=11 device=1 cardbus=1)
PCI configuration changed (bridge=7 devices=21)
[ PCI configuration end, bridges 7 devices 21 ]
```

Anbei noch die EFI mit Clover 5070 und die mit F4 gewonnenen originalen DSDT/SSDT.

Wie kann ich die DSDT anpassen?

Es geht hier um meine neue Errungenschaft, T61 mit Intelgrafik und 4 GB RAM

Können ggf. Bios-Einstellungen eine Rolle spielen?

Edit: übrigens ist der UpdateHelper in sekundenschnelle fertig. Ich glaube, der macht gar nix.

EDIT: Lösung lautet boot-args arch=x86_64, damit bootet Clover 5070 die 10.6.3

scheint somit gelöst.

Nur die passenden Kexte muss ich noch finden. Touchpad+tastatur laufen mit der config noch nicht.