

# MSi Z370 - MAG TOMAHAWK - Olarila Monterey installation IMPOSSIBLE

Beitrag von „griven“ vom 22. September 2021, 15:31

Since he "only" uses Ollarila's EFI I guess it's okay...

Check your config and disable [BrcmBluetoothInjector.kext](#) if present since it causes kernel panics on Monterey. If needed use BlueToolFixup.kext instead.