

Anfrage aus dem HWC - Liste für OOB Wifi /BT cards für Monterey

Beitrag von „GoodBye“ vom 31. Oktober 2021, 10:02

[DotWin](#)

Hallo DorWin,

habe soweit keine Probleme nach Warmstart, kann auch BT ein und aus schalten, versuche ihn mal aus und ein zu stecken wenn er nicht geht.

iPhoneTruth hat beim Baugleichen Rechner durch Einsatz meiner SSDT.aml und dem USBPorst.kext, im Standby die Lüfter endlich auch zum stehen gebracht, und der Wake funktioniert auch Perfekt.

Ich würde da auch noch mal ein Auge auf die USB Config und die SSDT werfen, die USB Config war nach Beta 6 ein wenig aufwendiger und durcheinander.

Ansonsten hast du ja die gleiche Peripherie 😊 Bis auf den Ferrari Prozessor/Board im Vergleich zu meinem alten Roß 🐎

P.S.: Was hast du denn für eine SMBIOS, und wie hast du SecureBootModel konfiguriert ?

[\[Sammelthread\] MacOS Monterey 12.x DEV-Beta Erfahrungen](#)

<https://github.com/acidanthera/BrcmPatchRAM/releases>

"v2.6.1

Improved BlueToolFixup compatibility with macOS 12b10

Fixed bluetooth support on MBP15,4 and other similar boards

Fixed bluetooth not working on macOS 12 after the first power cycle"

>> Bluetooth wird innernoch als Dongle erkannt, aber re-aktivieren funktioniert jetzt wieder.

Zitat [...] After the Bluetooth stack overhaul in macOS 12, we are still trying to get things in line. [...] BlueToolFixup makes most devices work on any Mac model with on-off support. Please note that Continuity and AirDrop features may not function correctly [for the time being](#) on macOS 12. [...]"

Quelle: <https://dortania.github.io/hac...acidanthera-november.html>