

Monterey Crash/Reboot je nach "4 Minuten ganz genau" mit Ryzen ASUS ROG STRIX B550-F GAMING (WI-FI)

Beitrag von „spacepilot3000“ vom 26. November 2021, 11:37

Wie gewünscht der Logfileauszug:

```
2021-11-26 11:30:48.447494+0100 0x38cc Error 0x0 0 0 kernel: (Sandbox) System Policy:
fseventsd(110) deny(1) file-read-metadata
/private/var/folders/zz/zyxvpxvq6csfxvn_n0000000000000/0/com.apple.LaunchServices.lv

2021-11-26 11:30:48.575122+0100 0x1609 Error 0x0 0 0 kernel: (Sandbox) System Policy:
fseventsd(110) deny(1) file-read-metadata
/private/var/folders/zz/zyxvpxvq6csfxvn_n0000000000000/0/com.apple.LaunchServices.lv

2021-11-26 11:30:48.575136+0100 0x1609 Error 0x0 0 0 kernel: (Sandbox) System Policy:
fseventsd(110) deny(1) file-read-metadata
/private/var/folders/zz/zyxvpxvq6csfxvn_n0000000000000/0/com.apple.LaunchServices.lv

2021-11-26 11:30:50.824783+0100 0x2e8d Default 0x0 0 0 kernel: (apfs) tx_flush:1171: disk2
xid 217056 tx stats: # 700 finish 703 enter 570 wait 78 42047us close 0us flush 4299us

2021-11-26 11:30:51.030036+0100 0x47a9 Default 0x0 0 0 kernel: (BlueToolFixup)
[IOUserUSBHostHIDDevice.cpp:897][0x10000abe] CompleteOutputRequest:0xe0005000

2021-11-26 11:30:51.030051+0100 0x1965 Error 0x0 0 0 kernel: (IOHIDFamily)
AppleUserUSBHostHIDDevice:0x10000abe ProcessReport:0xe0005000 2 0

2021-11-26 11:30:51.030066+0100 0x1965 Error 0x0 0 0 kernel: (IOHIDFamily)
IOHIDLibUserClient:0x10000ac7 setReport failed: 0xe0005000

2021-11-26 11:30:52.145625+0100 0x1a53 Default 0x0 0 0 kernel: memorystatus: assertion
priority 10 overrides priority 0 for ThumbnailExtension_macOS:742

2021-11-26 11:30:52.145759+0100 0x4b2b Default 0x0 0 0 kernel: memorystatus: assertion
priority 10 overrides priority 0 for ThumbnailExtension_macOS:742

2021-11-26 11:30:52.251328+0100 0x477e Default 0x0 0 0 kernel: memorystatus: set
assertion priority(0) target ThumbnailExtension_macOS:742

2021-11-26 11:30:52.414320+0100 0x4a5a Error 0x0 0 0 kernel: (Sandbox) Sandbox:
```

swcd(513) deny(1) system-fsctl _IO('h', 47)

2021-11-26 11:30:52.472748+0100 0x1742 Error 0x0 0 0 kernel: (Sandbox) System Policy:
fseventsd(110) deny(1) file-read-metadata
/private/var/folders/vh/51vzlrdd4ns__v_ggfn5yr480000gn/0/com.apple.SharedWebCredentials/swc.db

2021-11-26 11:30:52.472797+0100 0x1742 Error 0x0 0 0 kernel: (Sandbox) System Policy:
fseventsd(110) deny(1) file-read-metadata
/private/var/folders/vh/51vzlrdd4ns__v_ggfn5yr480000gn/0/com.apple.SharedWebCredentials/swc.db

2021-11-26 11:30:52.749194+0100 0x1609 Error 0x0 0 0 kernel: (Sandbox) System Policy:
fseventsd(110) deny(1) file-read-metadata
/private/var/folders/vh/51vzlrdd4ns__v_ggfn5yr480000gn/0/com.apple.SharedWebCredentials

2021-11-26 11:30:52.749224+0100 0x1609 Error 0x0 0 0 kernel: (Sandbox) System Policy:
fseventsd(110) deny(1) file-read-metadata
/private/var/folders/vh/51vzlrdd4ns__v_ggfn5yr480000gn/0/com.apple.SharedWebCredentials

2021-11-26 11:30:52.917354+0100 0x38cc Error 0x0 0 0 kernel: (Sandbox) System Policy:
fseventsd(110) deny(1) file-read-metadata
/private/var/folders/vh/51vzlrdd4ns__v_ggfn5yr480000gn/0/com.apple.SharedWebCredentials

2021-11-26 11:30:52.917385+0100 0x38cc Error 0x0 0 0 kernel: (Sandbox) System Policy:
fseventsd(110) deny(1) file-read-metadata
/private/var/folders/vh/51vzlrdd4ns__v_ggfn5yr480000gn/0/com.apple.SharedWebCredentials

2021-11-26 11:30:52.917552+0100 0x38cc Error 0x0 0 0 kernel: (Sandbox) System Policy:
fseventsd(110) deny(1) file-read-metadata
/private/var/folders/vh/51vzlrdd4ns__v_ggfn5yr480000gn/0/com.apple.nsurlsessiond/E8C9768780A371F3665

Reboot

2021-11-26 11:31:53.000000+0100 0x0 Timesync 0x0 0 0 === system boot: 8A92C9F6-CEC0-4DC3-86C2-101B4A4BDE14

2021-11-26 11:31:53.000000+0100 0x0 Timesync 0x0 0 0 === log class: in-memory begins

2021-11-26 11:31:53.000172+0100 0x0 Default 0x0 0 0 kernel: Darwin Kernel Version 21.1.0:
Wed Oct 13 17:33:23 PDT 2021; root:xnu-8019.41.5~1/RELEASE_X86_64

2021-11-26 11:31:53.020470+0100 0x0 Default 0x0 0 0 kernel: pmap_startup() delaying
init/free of page nums > 0x200000

2021-11-26 11:31:53.049282+0100 0x0 Default 0x0 0 0 kernel: pmap_startup() init/release

time: 28806 microsec

2021-11-26 11:31:53.049285+0100 0x0 Default 0x0 0 0 kernel: pmap_startup() delayed
init/release of 10628309 pages

Das herausnehmen der KEXTE für WLAN und LAN ändert irgendwie nix. Bleibe dran.